

Field Assembly Connector

09


Pigtail and patch-cord Field Assembly Connector

Features

- Can be assembled on fiber or cable sheath
- Easy assembly, no special tools required
- The connection can be verified easily after assembly

Application

- Fiber Outlets
- Fiber Termination Box
- Fiber DP/NAP Box




Specifications

Item	Specifications
Connector type	UPC or APC
Insertion loss (dB)	Maximum≤0.50; tpical≤0.3
Return loss (dB)	UPC≥50; APC≥55
Tensile load (N)	≥20
Working temperature (°C)	-40~+70

Classification

Product type	Mechanical Field Assembly Connector
Adaptor type	SC
UPC/APC	UPC APC



Specifications

Item	Specifications
Connector type	UPC or APC
Insertion loss (dB)	Maximum ≤0.50; typical ≤0.25
Return loss (dB)	UPC≥50; APC ≥55
Tensile load (N)	≥20
Working temperature (°C)	-40~+70

Classification

Product type	Mechanical Field Assembly Connector
Adaptor type	LC
UPC/APC	UPC APC

Assembly Toolkit

